



BLUE HAWK MI


Data Should Be Free And Accessible

We hear that Mechanical Integrity (MI) is a headache. A lot.

It doesn't have to be.

Instantly boost your MI program through a state-of-the-art IDMS (Inspection Data Management System).

Blue Hawk MI instantly completes the modernization of your MI program.



Blue Hawk MI (IDMS)



BLUE HAWK MI

Blue Hawk MI is our WebApp analytics platform for evaluating and interpreting Mechanical Integrity (MI) data. Often referred to in the industry as an Integrity Data Management System (IDMS), our solution departs from bloated offerings of yesterday and delivers a highly customizable, fit for purpose, on-demand MI WebApp. We're driven by efficiency and Blue Hawk MI sets the foundation for the next generation of Mechanical Integrity data management. Compliance has never been so easy.

- Modernized Inspection Data Management System (IDMS)
- Intuitive WebApp – navigate your data with the ease of your browser
- Dynamic dashboards – effortlessly access expressive and interactive dashboards
- Google Maps built-in to engage with your data using the best tools available
- PSM Compliant following industry RAGAGEP
- Advanced algorithms including inspection and construction standards to quickly calculate your inspection intervals
- On-demand data exporting – finally, accessing your data made easy!
- Highly customizable platform that's customized to each client's requirements
- Risk-based inspection (RBI) ready

Our web-based portal provides easy access to all your data, MI records, facility documentation, mapping of asset locations, and more. We've heard repeatedly how data is held hostage or gets 'lost'. We've heard the complaints in the industry about unexplainable minimum thickness results and inspection intervals. That's exactly what we're striving to reinvent the MI process. From intuitive access, single click data exports to spreadsheet, to dynamic maps and tables, this is a whole new level of ease and efficiency.

But don't just take our word for it, schedule your demo today!

API 570 INSPECTION REPORT

Inspection Date: 26-Apr-2020 10:13 AM
Job Number: 901
QR Code: NW 1505916
Points Monitored: 332-55
Process: Produced Water
WPS: 100
Subcode: 20 Station
Inspector: 78-Apr-2020 09:13 AM
Date & Time: 020
Job Number:

Owner (Company):
Location:
Line Number:
Circuit Reference:
No.:
Utag:

Sector: Wastewater
Location: Wastewater
System: Produced Water
Process: Produced Water
WPS: No
Subcode: No
Inspector: No
Date & Time: No
Job Number: No

Caution CMA
Watch CMA
Good CMA

Asset Name	Component Type	Normal Thickness	Nextest Date	Asset Corrosion Rate	Asset Retirement Date	Remaining Life (Years)	Retirement Date
Badger Central Gathering Facility	Cylindrical Shell	0.375	09/01/2020	0.3232	09/12/2019	0.5	01/29/2022
Badger Central Gathering Facility	Cylindrical Shell	0.375	05/01/2020	0.3232	07/12/2019	0.5	01/29/2022
Badger Central Gathering Facility	Cylindrical Shell	0.375	06/20/2019	0.3232	09/12/2019	0.5	01/29/2022
Badger Central Gathering Facility	Ellipsoidal Head	0.375	06/20/2019	0.2849	04/30/2019	1.03	01/29/2022
Badger Central Gathering Facility	Ellipsoidal Head	0.375	06/20/2019	0.2849	10/29/2022	1.93	01/29/2022
Badger Central Gathering Facility	Ellipsoidal Head	0.375	06/20/2019	0.2849	04/30/2019	1.03	01/29/2022
Badger Central Gathering Facility	Ellipsoidal Head	0.375	06/20/2019	0.2849	10/29/2022	1.93	01/29/2022
Badger Central Gathering Facility	Ellipsoidal Head	0.375	06/20/2019	0.2849	04/30/2019	1.03	01/29/2022
Badger Central Gathering Facility	Ellipsoidal Head	0.375	06/20/2019	0.2849	10/29/2022	1.93	01/29/2022

www.integrityepc.com
info@integrityepc.com
(303) 228-7067
600 17th St., Suite 2800, Denver, CO 80202